



Map produced by the NRVPC using VGIN data. March, 2009

Site Specific Details:

This intersection has poor sight distance greatly attributed to rolling vertical grade along the east and west bound Route 11 roadway corridors. The intersection currently has under 500 ft. of site distance for west bound entry and is located in the taper of an existing turning lane. The intersection needs to be formally evaluated to improve the safety when exiting Novell Road and entering Route 11.

General Notes:

1. The following intersection has been identified as a safety concern as a result of congestion or poor sight distance. The proposed improvements are conceptual only and should be evaluated and designed by a licensed engineer.
2. All sign and roadway improvements shown are conceptual only, and shall be designed in accordance with the latest edition of the Virginia Department of Transportation Roadway Design Manual.
3. Sight Distance is estimated and should be field verified for accuracy.

Legend

SD	Sight Distance
	Study Area



Field photo of existing intersection of Novell Road and Route 11. View of photo is to the east from center of west bound turn lane.



Field photo of existing intersection of Novell Road and Route 11. View of photo is to west from the center of Novell Road Exit Lane.



Field photo of existing intersection of Hatcher Road and Route 11. View of photo is to the east from the center of Novell Road exit lane.